


INSTALLATION INSTRUCTIONS

TCC PUMP ORIFICE CAPSULE for 4L60E '96-up

 **NOTE:** Under severe overheating conditions, the original plastic TCC Orifice Insert (OEM 8634284) will melt and clog the orifice.

77831

To Replace: Using a brass, copper or plastic hammer, drive the new TCC Pump Orifice Plug into the original orifice. No drilling is required.

